

AGREEMENT FOR ACCESS TO PROPERTY

This Agreement for Access to Property ("Agreement"), between the Housing Authority of the City and County of Denver ("Housing Authority"), and the United States Environmental Protection Agency ("EPA"), provides as follows:

- In exchange for the mutual promises in this Agreement, the Housing Authority grants permission to officers, employees, and authorized representatives of EPA to enter and access the property owned by the Housing Authority located at 3411/3401 Arapahoe Street, Denver, Colorado, 80205 (the "Site") for the purpose of taking samples of soil on the Site.
- 2) The Housing Authority acknowledges that the sampling of soil on the Site is undertaken pursuant to EPA's response and enforcement responsibilities under the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA or Superfind), 42 U.S.C. § 9601 et seq.
- 3) EPA shall provide the Housing Authority a copy of all results and analyses of the soil samples taken at and all testing activities conducted on the Site within 14 days of receiving the results or analyses.
- 4) EPA shall provide the Housing Authority notification by telephone at least 48 hours in advance of entry on the Site by calling <u>Laura love !</u> at 120-932-3074.
- To the extent permitted by law, EPA will indemnify and hold harmless the Housing Authority and its lessees from any claims (including reasonable attorneys fees and related expenses) arising from the alleged acts or omissions of EPA or its employees, officers, and authorized representatives, which occurred or are alleged to have occurred in connection with EPA's exercise of its rights set forth herein.
- This Agreement shall expire 60 days after the date of the last signature below, unless extended in writing by the parties.

unless extended in writing by the	he parties.	•	r
Housing Authority of the City & Coun	nty of Denver		
By: Saludor Curpice Its: Executive Director Date: October 7, 2005	(gr.)		
United States Environmental Protection		1 -	
By: Its:	· (by G)	Forz	9/32/
Date:	21.5. ARMY	For M USEPA Lores Of	Eyazs
	FOR		

	3411 Arapahoe St.
· · · · · · · · · · · · · · · · · · ·	
	1 NB-3411-AP-01 A green
	/ VB-3411-AP-02 A yellow
+	V 18-3411-AP-03 - AP-03
	X D Section Grido Points
- - - - - - - - - -	*3
	Δ 130 10
	03 143 12
*	Δ D D 364/30 = 12.133.
	Pyan Pyan
4	
	0245 P 0250 A 0155 +
Δ	
	25
	[6817]41

Evergreen Analytical, Inc.

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Project ID 213001.01 Date Received: 10/17/05

Lab Order:

05-7859

Date Prepared: 10/20/05 Units:

mg/Kg

Metals Arsenic

Method: SW6010

Prep Method: SW3050

			Date	Date				
Lab (D	Client ID	Matrix	Collected	Analyzed	Results	LQL	<u>D</u> F	_
05-7859-05A	VB-3339-HB-01	Soil	10/14/05	10/21/05	5.4	4.0	1	
05-7859-06A	VB-3339-HB-02	Soil	10/14/05	10/21/05	5.5	4.1	1	
05-7859-07A	VB-3339-HB-03	Soil	10/14/05	10/21/05	6.7	4.1	1	
05-7859-08A	VB-3724-DO-01	Soil	10/14/05	10/21/05	5.9	4. l	1	
05-7859-09A	VB-3724-DO-02	Soil	10/14/05	10/21/05	5.2	4.2	1	
05-7859-10A	VB-3724-DO-03	Soil	10/14/05	10/21/05	5.1	4.0	1 .	4
05-7859-11A	VB-4330-DW-01	Soil	10/14/05	10/21/05	4.5	4.0	1	
05-7859-12A	VB-4330-DW-02	Soil	10/14/05	10/21/05	4.2	4.0	1	
05-7859-13A	VB-4330-DW-03	Soil	10/14/05	10/21/05	4.6	4.2	1	
05-7859-14A	VB-3411-AP-01	Soil	10/14/05	10/21/05	27	4.0	1	
05-7859-15A	VB-3411-AP-02	Soil	10/14/05	10/21/05	5.0	4.0	1	
05-7859-16A	VB-3411-AP-03	Soil	10/14/05	10/21/05	4.9	4.2	1	
05-7859-17A	VB-3401-AP-01	Soil	10/14/05	10/21/05	ប	4.2	1	
05-7859-18A	VB-3401-AP-02	Soil	10/14/05	10/26/05	4.2	4.0	1	
05-7859-19A	VB-3401-AP-03	Soil	10/14/05	10/26/05	U	4.1	1	
05-7859-20A	VB-3639-DE-01	Soil	10/13/05	10/26/05	4.5	4.1	1	
05-7859-21A	VB-3639-DE-02	Soil	10/13/05	10/26/05	5.3	4.0	1	
05-7859-22A	VB-3639-DE-03	Soil	10/13/05	10/26/05	6.2	4.1	1	

Analyst

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

H - Sample exceeded analytical holding time

J - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected

X - See case narrative

* -Value exceeded the Maximum Contamination Level (MCL)

Approved

Definitions: DF - Dilution Factor

PF - Prep Factor

LQL - Lower Quantitation Limit

Print Date: 10/28/05

Evergreen Analytical, Inc.

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Project ID 213001.01 Date Received: 10/17/05

Lab Order: Date Prepared: 10/20/05

05-7859

Units:

mg/Kg

Metals Lead

Prep Method: SW3050 Method: SW6010

Michiga: 244 AAIA								
			Date	Date				
Lab ID	Client ID	Matrix	Collected	Analyzed	Results	LQL	DF	_
05-7859-01A	1450-001-SCC	Soil	10/17/05	10/21/05	12	5.8	1	
05-7859-02A	1450-002-SCC	Soil	10/17/05	10/21/05	14	5.8	1	
05-7859-05A	VB-3339-HB-01	Soil	10/14/05	10/21/05	180	5.8	1	
05-7859-06A	VB-3339-HB-02	Soil	10/14/05	10/21/05	120	6.0	1	
05-7859 - 07A	VB-3339-HB-03	Soil	10/14/05	10/21/05	180	5.9	ı	
05-7859 - 08A	VB-3724-DO-01	Soil	10/14/05	10/21/05	220	5.9	1 '	٠.
05-7859-09A	VB-3724-DO-02	Soil	10/14/05	10/21/05	190	6.1	1	
05-7859-10A	VB-3724-DO-03	Soil	10/14/05	10/21/05	190	5.8	1	
05-7859-11A	VB-4330-DW-01	Soil	10/14/05	10/21/05	150	5.9	1	
05-7859-12A	VB-4330-DW-02	Soil	10/14/05	10/21/05	130	5.8	l	
05-7859-13A	VB-4330-DW-03	Soil	10/14/05	10/21/05	120	6.1	1	
05-7859-14A	VB-3411-AP-01	Soil	10/14/05	10/21/05	120	5.8	1	
05-7859-15A	VB-3411-AP-02	Soil	10/14/05	10/21/05	120	5.8	t	
05-7859-16A	VB-3411-AP-03	Soil	10/14/05	10/21/05	180	6.1	1	
05-7859-17A	VB-3401-AP-01	Soil	10/14/05	10/21/05	36	6.1	1	
05-7859-18A	VB-3401-AP-02	Soil	10/14/05	10/26/05	90	5.9	l	
05-7859-19A	VB-3401-AP-03	Soil	10/14/05	10/26/05	47	5.9	1	
05-7859-20A	VB-3639-DE-01	Soil	10/13/05	10/26/05	180	6.0	1	
05-7859-21A	VB-3639-DE-02	Soil	10/13/05	10/26/05	300	5.9	1	
05-7859-22A	VB-3639-DE-03	Soil	10/13/05	10/26/05	220	6.0]	

Analyst

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

H - Sample exceeded analytical holding time

I - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected

X - See case narrative

* -Value exceeded the Maximum Contamination Level (MCL)

Definitions: DF - Dilution Factor

PF - Prep Factor

LQL - Lower Quantitation Limit

Print Date: 10/28/05



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 8

999 18TH STREET- SUITE 300 DENVER, CO 80202-2466 Phone 800-227-8917 http://www.epa.gov/region08

Ref: 8EPR-SR

December 7, 2005

HUD C/O LAURA CORRELL P.O. BOX 40305 DENVER CO 80204

RE: 3411 ARAPAHOE ST

Dear Owner.

As part of the VB/I-70 Superfund Site investigation, we recently took soil samples at your property to find out if there is too much lead or arsenic in your yard. The results show that your property does not require a cleanup. The levels of both lead and arsenic are below our cleanup levels. The soil sampling results for your property are as follows:

ADDRESS: 3411 ARAPAHOE ST

EPA Cleanup Levels

Lead

140 parts per million (ppm)

above 400 ppm

Arsenic

27 ppm

above 70 ppm

This means that your property is not considered by EPA to be part of the VB/I-70 Superfund Site. EPA does not believe that further measures are necessary. You and your family are not at significant risk from arsenic through ordinary contact with soil in your yard while playing, working, gardening, etc. Please note that there may be small areas in your yard, particularly near your house, that may have higher levels of lead due to peeling, external lead-based paint. EPA encourages all owners of older properties to take reasonable precautions regarding lead-based paint.

For further information, please feel free to contact EPA Community Involvement Coordinators Jennifer Chergo at (303) 312-6601 or Patricia Courtney at (303) 312-6631.

Sincerely,

Victor Ketellapper

Remedial Project Manager

The Environmental Protection Agency, Region 8